CERTIFICATE

NAME OF WORK : Desilting of SWD drain at Kammagondanahalli near Jarakabande kaval slum primary drain in Ward no. 12, in Shettyhalli Sub-Division

JOB NO : 012-12-000015

WORK ORDER NO : No. EE/DD/WO/93/11-12, dated: 05/08/2011

As per the orders of the Commissioner vide No. comm. PR/C1-186/2015-16, dated: 12/06/2015, warning notices have been issued to the concerned Engineers for not maintaining Daily Labour Report (DLR), Log book and recording work turned out details for the above work with an instruction to maintain and record above documents for such works in future. Since the said work is carried out and completed ...2 (two).. years back, the bill may be considered for payment.

Chief Engineer
Dasarahalli Zone
BBMP, Bangalore

ಮುಖ್ಯ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬಿ